

Market Release Note

MRN-DLX900 V5.16.18

Product number: DLX900

Product version: V5.16.18

Release date: 27th July 2022

Bugs/Enhancements Resolved/Closed

The following issues were addressed in this release

| ID | Туре | Description |
|---------|--------|--|
| XC-1122 | DLX900 | Fixed inconsistencies in configuration data when connected to NXX-8 AU panel |
| XC-1123 | DLX900 | Fixed inconsistencies in configuration data when connected to NXX-4 AU panel |
| XC-1125 | DLX900 | Fixed the number of displayed zones when connected to version 09-40 of the xGenConnect panel |

Known Issues

The following issues are known in this release

| ID | Status | Description |
|---------|--------|--|
| XC-1125 | Minor | The DLX900 software can intermittently failed to send menus to version 9-38 of the NXX-8 panel |
| XC-1126 | Minor | Some configuration pages such as Device info/System timer/Download access code/Service time/UltraSync pages can intermittently display the wrong information on first connection after changing panels or switching between existing accounts with version 9-38 and 9-40. It is advised to close all Device info/System timer/Download access code/Service time/UltraSync windows and select "Retrieve all data" when switching from a device with version 9-40 firmware to another device with an older firmware version. |



•