Market Release Note

MRN-TS91016-V10-06-R3

Product number:	TS1016, TS1016B, TS1016SE, TS1016SEB
Product description:	Challenger10, ChallengerSE
Product version:	V10-06-8435
Affected parts:	n/a
Release date:	6th July 2015

Resolved Issues

- Resolved issue where relays on second LAN could not be controlled

- Updated default values for new communication path options to ensure connectivity is maintained after firmware upgrade.

- Users are no longer set to void after firmware upgrade.

Known issues

- Any Challenger10 or ChallengerSE panel upgrading from a version of firmware older than V10-06 will be classed as a new panel type when updated to this firmware. This means that the panel record will need to be converted to the new type in the software (Security Commander, Titan, Forcefield). Please refer to the manuals or call support if further information is required.

- Non-polled peripherals are not backed up or restored when using the SD card.

Downloads

Firmware file – SREC

Firmware file - ZIP