Market Release Note

MRN-TS9100-72-B52

Product number:	TS9100, TS9120
Product description:	Forcefield
Product version:	TS9100 7.2 Build 52
Release date:	10 February 2016

Interlogix is pleased to announce the availability of Forcefield 7.2, Build 52. This build offers a number of resolved issues. For new features released in Forcefield 7.2, please refer to the Market Release Notice issued on 20 November 2015.

Resolved Issues

- Resolved issue where users would not download to all panels
- Resolved issue where Door & Floor Groups could not be deleted
- Resolved issues with 'Search and Select' screens locking up or disabling navigation buttons in certain conditions
- Resolved issue where Mount Server process would crash under certain conditions

Documentation

Marketing Collateral	Forcefield datasheet
	Tecom software comparison matrix
	TruVision video plugin datasheet
	Genetec video plugin datasheet
Technical Manuals	Forcefield Installation and Setup Manual
	Forcefield Operators Manual
	Forcefield External Interfaces Manual
	Forcefield Licence Form
Software downloads	Visit www.interlogix.com.au/downloads to download the latest software and firmware versions.

Known issues

- Serial printing to a third party system sometimes stops working when the system is under heavy load. As a result, occasionally the server will need to be restarted to resume functionality.