

Market Release Note

MRN-TS97101-B9

Product number: TS97101

Product description: Security Commander 2.2

Product version: TS97101 2.2 Build 9

Release date: 10th June 2015

Interlogix is pleased to announce the immediate availability of Security Commander 2.2.

New features

Security Commander 2.2 offers the following improvements:

- Support for new features in Challenger10 V10-06 firmware. Major enhancements include:
 - Device descriptions stored in the panel
 - Automation Zones (C-Bus integration)
 - 3G Communication Card (configuration only)
 - See Challenger MRN for full list of changes in new firmware
- Support for the new ChallengerLE panel
- Improved user interface
 - All forms are now part of a tabbed layout
 - Forms can be configured into custom layouts
 - Layouts can be for single or multiple monitors
 - Layouts are remembered when the operator logs out and then recalled when the operator logs back into the software
- Updated Person and Badge forms
 - System will now auto-generate and assign badges to newly created person records
 - Operators can now view badges that have been assigned to a person record from the person form
 - Added ability to show PIN on both Person and Badge forms
 - Added auto-incrementing field for person number in Person form
- Door group creation has been improved with the ability to assign multiple doors to a door group with a single operation

- Photo ID module is now included in main installation which means users no longer have to separately install the photo ID package on each machine.
- Added option to filter User in Door/Floor/Alarm Group reports by facility
- Added option to filter Door and Floor Access reports by facility
- Badge records can now be saved with an issue date that is in the past. This allows the expiry date to be dynamically updated without affecting the issue date.

Documentation

Marketing Collateral	Security Commander datasheet
	Tecom software comparison matrix
	Tecom (Security Commander) A&E Specification
	Security Commander overview presentation
	TruVision video plugin datasheet
	Genetec video plugin datasheet
Technical Manuals	Security Commander Administrators Manual and Operation Guide
	Security Commander Installation Manual
	Security Commander API Installation and Operation Manual
	Security Commander CCTV Interface Guide
	Security Commander SQL Server Mirroring Guide
	Security Commander Photo ID User Guide
Software download	Security Commander 2.2, build 9

Issues resolved in this release

- Forms no longer make a 'beeping sound' every time they are opened
- Person records imported through the CSV import with the same profile description are no longer linked. For example, changing a door group for one person will no longer change the group for all users that were imported.
- When person records are imported through the CSV import the system will no longer create a new facility called 'Ignore Facilities' if 'Ignore Facilities' is in the facility field. Instead, the system will not assign a facility to the person as per normal form operation.
- Resolved issue in the History report where sometimes it would still filter by a particular person even if ALL was selected in the drop down filter.
- Anti-passback alarms now work correctly

Known issues

- Activation codes from previous versions of Security Commander will not work with Security Commander 2.2. This is because the encoding of the activation code needed to be changed. Customers who have an existing code are still eligible to upgrade to Security Commander free of charge. However, they will need to call Interlogix to obtain an updated activation code.
- On rare occasions, the photo ID module will produce errors with Windows 8 installations.