

Market Release Note

MRN-TS1016-V10-06-R7

Product number: TS1016, TS1016B

Product description: Challenger10

Product version: V10-06.17295

Affected parts: TS1016, TS1016B

Release date: 21 March 2018

New features

- Option to clear comms path event buffer on disarm

Documentation and Downloads

Marketing Collateral	Challenger10 datasheet
	Tecom Compatibility Matrix
Technical Manuals *	Challenger Series Programming Manual
	Challenger Series Users Manual
	Challenger Series Administrators Manual
	Challenger Series Installation and Quick Programming Manual
Firmware Download Challenger10/SE	Challenger firmware – ZIP file
	Challenger firmware - SREC file

All downloads can be found at www.interlogix.com.au/downloads

* Technical manuals can be downloaded via the [Interlogix Support portal](#). Please note some documents are protected via login credentials.

Known issues

- Any Challenger10 or ChallengerSE panel upgrading from a version of firmware older than V10-06 will be classed as a new panel type when updated to this firmware. This means that the panel record will need to be converted to the new type in the software (Security Commander, Titan, Forcefield). Please refer to the manuals or call the technical support department if further information is required.
- Non-pollled peripherals are not backed up or restored when using the SD card.
- When using a TS1084 IUM, user names are not stored in the panel.
- When the option for 'Enable V8 Numbering' is toggled, input programming and numbering will not be altered. If this option is set incorrectly, inputs may not function as expected, and input names may appear to be incorrect.